
Smoke and Dye Testing Summary

High Level Sewershed

Run Summ	ary 	Date Inspected	Company / Super.		Ground Condition	Notification		
Test ID	Test Type			Nearest MH		Made?		
D1028-168	Dye	4/27/2009	ADS/TM	S11GG_021MH	Dry	NA		
Address 1603 Bloomingdale Road		Location	Curb	Status P	ublic	Source	Catch Basin	



Smoke and Dye Testing Summary

High Level Sewershed

Run Summ Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?	1	
D1028-168	Dye	4/27/2009	ADS/TM	S11GG_021MH	Dry	NA		
Address 1603 Bloomingdale Road			Location	Curb	Status P	ublic	Source	Catch Basin